

LAND CORNER RECORD

Index: K-8	Corner: NE 1/16 SECTION 17			State of Indiana - Hoosier National Forest
Section: 17	Township: 7N	Range: 1E	P.M.: 2nd	County: Monroe
Coordinate:	Lat./N:		Lon./E:	Datum:

CORNER HISTORY: (Chronological history of corner)

1.) Date of Survey:	Surveyor:	Monument:	Recording Information:		Monument Photograph:
4/1980	T. Cummings	Sandstone	USFS Records		
Reference Objects:	Species:	Diameter:	Bearing:	Distance:	
Evidence Found:					
Monument Found:	5"x5" stone w/ "+", top broken off, base firm.				
2.) Date of Survey:	Surveyor:	Monument:	Recording Information:		
Reference Objects:	Species:	Diameter:	Bearing:	Distance:	
Evidence Found:					
Monument Found:					

ACCESSORIES: Bearing and distances from monument to witness object.

Reference Objects:	Object or Tree Species:	Diameter:	Bearing:	Distance:
	W. OAK	14"	S 88° W	22.40'
	B. OAK	18"	S 23° W	18.54'
	B. OAK	14"	S 30° E	29.18'
Monument Found or Set:	Replaced broken stone with a 3" aluminum monument with disk, set 0.6' above grade.			


MONUMENT SKETCH



NARRATIVE REFERENCE:

The monument is a 3" aluminum monument with disk, set 0.6' above grade, ± 130' west of the top of ridge and on a Westerly facing grade.

SECTION DIAGRAM



Corner Location = ●

PERPETUATION RECORD:

Replaced broken stone with a 3" aluminum monument with disk, set 0.6' above grade, piled rocks around and painted red. The corner stone was accepted as the 1/16 corner, no legal survey records were found to the contrary. Three new bearing trees were established.

Marty J James, LS#29900010, Bob Stone, Darren Norrington and BRG survey crew were present at time stone was replaced.

Accepted by the Monroe County Surveyor Review Board on August 6, 2019.

Section: 17

Prepared By: BRG # 7308

Date: 12/27/2012

Index No. K12
(Alphabetical - Numerical)LAND CORNER RECORD
(RECTANGULAR SURVEYS)

R9-7100-74 (Rev. 5/80)

826-531

T. 7N R. 1E Mer. N.F. _____ County Monroe State IN.
NE 1/4 Corner common to sections 16 and _____

EXISTING SURVEYS

Original Government Survey

Year surveyed _____

Original monument _____

(Wood post, stone, pile of stones, pipe, etc.)

Original Evidence Found

Year of search _____ By _____

Monument found _____


Original Bearing Trees Found

Evidence of Subsequent Corner Restoration Found

Search _____ By _____

Bearing Trees, Reference Objects

Distance _____



Sketch

○ Corner ■ F.S. Land

At time of search:

1. Did you have the record description?

Yes _____ No ☒

2. How was search area located?

Pacing, chaining, photos, maps,
etc. map

3. Man hours spent in search _____

4. Do you think additional search might

recover evidence? Yes _____ No ☒

5. Signature _____

Relation of Evidence to Record Features Along Section Lines

Section line to sections _____

Object _____

Record distance _____

Measured distance _____

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc. Cite source of testimony if any. limestone - 5" x 10"
top 1/3 broken + lying on top of stone.
large + in top, no other marks. Stone
well set. 6" w of 10" chest. oak with
one strand of wire looped through center.
Evidence of fire approx. 75' to SW.
N running tree line 5' to E.

Perpetuation Record

Monument and accessories established. Include brief description of area. _____

B.T.
R. oak
12"N 84° E
18' 8.5"B.T.
T. Pop.
8"N 38° W
17' 4.5"

Certified corner restoration certificate prepared:

Yes _____ No _____

Filed in county records at _____

Date _____ County Document No. _____

Identified on aerial photo No. _____

Which is filed at _____